

# OPERATING INSTRUCTIONS

**Manufacturer:**

Ripley® Miller

**Product Name:**

Ripley® Miller FO-R12 Cable Jacket Stripper for 12-Fiber Ribbon

**Manufacturer Part Number:**

FO-R12

▶ [Click here for more details on the Ripley® Miller FO-R12 Cable Jacket Stripper for 12-Fiber Ribbon](#)

## FO-R12 Ribbon Fiber Jacket Stripper Operating Instructions

**Warning!** This tool should not be used on live electrical circuits. It is not protected against electrical shock! Always use OSHA/ANSI or other industry approved eye protection when using tools. This tool is not to be used for purposes other than intended. Read carefully and understand instructions before using this tool.



This tool is designed to easily remove the jacket from 12-count fiber optic cable, without damaging the underlying fiber. Here are a few suggestions to help you use it safely and efficiently.

**Step 1: Remove the Jacket**

1. Place the jacketed ribbon fiber in the stripping station located in the middle of the tool.
2. Close the tool completely, keeping ribbon fiber securely in the stripping station to pierce through the jacket.
3. Grasp the jacket between your thumb and fingers and pull the jacket to remove it. This method is generally preferred instead of using the tool to force or strip the jacket, which can cause the jacket to bind up on the fiber or Kevlar® yarn.

**Step 2: Cut the Kevlar Strengthening Yarn**

Use the Miller 86 1/2SF Kevlar® Shears or Miller FOKC, both designed to give fast, clean cuts to cut the Kevlar® strengthening yarn.

**Contact the professionals at Fiber Optic Center for a quote or to get more details.**

[focenter.com](http://focenter.com) • 508-992-6464 | (800) 473-4237 • [sales@focenter.com](mailto:sales@focenter.com)

23 Centre Street • New Bedford, MA 02740 USA

Product specifications and data are subject to change without notice. FOC last update 12/22/2025.