


OPERATING INSTRUCTIONS

**Manufacturer:**

Ripley® Miller


Product Name:

Ripley® Miller MSAT® 16-Channel Mid-Span Fiber Buffer Tube Slitter (1.0mm-3.0mm)


Manufacturer Part Number:

MSAT-16

▶ [Click here for more details on the Ripley® Miller MSAT® 16-Channel Mid-Span Fiber Buffer Tube Slitter \(1.0mm-3.0mm\)](#)



[Operating Instructions](#)



[Blade Replacement Instructions](#)


Contact the professionals at Fiber Optic Center for a quote or to get more details.

focenter.com • 508-992-6464 | (800) 473-4237 • sales@focenter.com

23 Centre Street • New Bedford, MA 02740 USA

Product data subject to change without notice.. FOC last update 12/17/2025.

OPERATING INSTRUCTIONS

**Manufacturer:**

Ripley® Miller

Product Name:

Ripley® Miller MSAT® 16-Channel Mid-Span Fiber Buffer Tube Slitter (1.0mm-3.0mm)

Manufacturer Part Number:

MSAT-16


▶ Click here for more details on the Ripley® Miller MSAT® 16-Channel Mid-Span Fiber Buffer Tube Slitter (1.0mm-3.0mm)

MSAT™ 16

TOOL OPERATING INSTRUCTIONS



A RIPLEY® BRAND



>> Return to Page 1

Contact the professionals at Fiber Optic Center for a quote or to get more details.

focenter.com • 508-992-6464 | (800) 473-4237 • sales@focenter.com

23 Centre Street • New Bedford, MA 02740 USA


Product data subject to change without notice.. FOC last update 12/17/2025.

MSAT™ 16


TOOL OPERATING INSTRUCTIONS




A RIPLEY® BRAND




1 SIZE
TUBE



2 SELECT
SETTING



3 INSERT
TUBE



4 SHAVE
TUBE

>> Return to Page 1


Contact the professionals at Fiber Optic Center for a quote or to get more details.

focenter.com • 508-992-6464 | (800) 473-4237 • sales@focenter.com

23 Centre Street • New Bedford, MA 02740 USA

Product data subject to change without notice.. FOC last update 12/17/2025.

OPERATING INSTRUCTIONS

**Manufacturer:**

Ripley® Miller

Product Name:

Ripley® Miller MSAT® 16-Channel Mid-Span Fiber Buffer Tube Slitter (1.0mm-3.0mm)

Manufacturer Part Number:

MSAT-16


▶ Click here for more details on the Ripley® Miller MSAT® 16-Channel Mid-Span Fiber Buffer Tube Slitter (1.0mm-3.0mm)

MSAT™ 16

BLADE REPLACEMENT INSTRUCTIONS



A RIPLEY® BRAND



>> Return to Page 1

Contact the professionals at Fiber Optic Center for a quote or to get more details.

focenter.com • 508-992-6464 | (800) 473-4237 • sales@focenter.com

23 Centre Street • New Bedford, MA 02740 USA

Product data subject to change without notice.. FOC last update 12/17/2025.